



Worldwide repairs carried out with PolymerMetall®

REP-# 039



Oil flew through a crack at the cable terminal funnel of a block transformer. The repair was carried out by the method of direct-MM-bonding with MM-metal oL-steelceramic, Hardener red and Hardener yellow.

MultiMetall
the MetalExistenceCompany®