




Worldwide repairs carried out with PolymerMetal®

REP-# 029



Repair of a grinding machine in a cement company. The damage, a worn out bearing housing, was repaired with MM-metal SS-steelceramic and Hardener yellow. Herewith the previous repair method „resurfacing by welding“ was replaced.

MultiMetall
the MetalExistenceCompany®