



Worldwide repairs carried out with PolymerMetal®

REP-# 021



Cracked welding seams in a silo tank were repaired by using MM-metal SS-steelceramic and Hardener yellow.

MultiMetal
the MetalExistenceCompany®