



Worldwide repairs carried out with PolymerMetal®

REP-# 056



Sealing of a steam pipe under pressure by using MM-metal UW and Hardener UW3. Reason for the repair were cracks of welding seams caused by vibration at a working pressure of 2 bar and a temperature of 90 °C.

MultiMetal
the MetalExistenceCompany®