





Worldwide repairs carried out with PolymerMetal®

REP-# 096



Repair of a propeller shaft near the stuffing box packing by using Ceramium pasty with Hardener CE.

MultiMetal
the MetalExistenceCompany®