




Worldwide repairs carried out with PolymerMetal®

REP-#150



A broken pump casing was repaired with the help of the PolymerMetal MM-metal SS-steelceramic.

**MultiMetal**  
the MetalExistenceCompany®