



*Worldwide repairs carried out with PolymerMetal®*

REP-#152



Onto a damaged area of an axle end MM-metal SS-steel, later MM-metal SS-steel 382 was applied to receive a higher surface quality. After curing, the work piece was machined down with a lathe to the desired diameter.

**MultiMetall**  
the MetalExistenceCompany®